



CDM HIGH RISK ASSESSMENT	
ITEM	RECOMMENDATION
Roof Structure and Cladding	To prevent fall, scaffolding or boarding of structural members required.
Roofs, Facades & Non Water Cooled	To prevent fall, scaffolding required.
External Wall (Below Upper Floor)	To prevent fall, scaffolding required.
Windows (Upper Floor)	To prevent fall, scaffolding required.
Plumbing in Loft	Scaffolding/Boarding required.
Preparation in situ of floor slabs	Scaffolding/Boarding required.
Roofs/Cladding	Mechanical measures on appropriate
Non Handling	Use Mechanical Equipment. See next 100 and work in specific handling. See schedule for weight.
Craneage	Temporary Propping required.
Health	Provide COSHH Assessment.
FOR ALL OTHER RISKS, REFER TO DETAILED DESIGN RISK ASSESSMENT PRODUCE.	
THIS DRAWING IS THE PROPERTY OF BETTERPLAN DESIGN LTD AND WILL BE RETURNED TO US IMMEDIATELY UPON ANY REQUEST FOR A FURTHER COPY. THE COPYRIGHT RESERVATIONS OF THE CLIENT OR BPD LTD IN WRITING COPYRIGHT©BETTERPLAN DESIGN LTD	



bpd Architecture
CIAT Registered practice
Suite 11, Hearle House, 5 East Terrace Bus Park, Euxton Lane
Euxton, Chorley, Lancashire PR7 6TB
Tel: 01257 220510
web: www.betterplan.co.uk
email: info@betterplan.co.uk



Chartered Institute of
Architectural Technologists
Registered Practice

Project
**Land at Unsworth Street, Tyldesley
Manchester M29 8NX**

Title
**OUTLINE HOUSE APPLICATION
Indicative floor plans and section**

Scale @ A1 1:50/1:100	Date Oct 2021	Ref Job 1047	Drawn MDB
Proj No 1047/UST/PL1	Rev -		